



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED (CD)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Melamine(108-78-1)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylacetamide(127-19-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Dodecamethylcyclohexasiloxane(540-97-6);C,C'-azodi(formamide)(123-77-3);4,4'-Isopropylidenediphenol(80-05-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Tris(2-chloroethyl) phosphate(115-96-8)
DOOR SUNROOF	DOOR	Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);Benzo(a)pyrene(50-32-8);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Imidazolidine-2-thione(96-45-7)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)

ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Ethylenediamine(107-15-3);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	TBBA(79-94-7);Boric acid(10043-35-3);Lead(7439-92-1);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-

		6);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED 5DR (CD 5DR)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Melamine(108-78-1)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylacetamide(127-19-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Dodecamethylcyclohexasiloxane(540-97-6);C,C'-azodi(formamide)(123-77-3);4,4'-Isopropylidenediphenol(80-05-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Tris(2-chloroethyl) phosphate(115-96-8)
DOOR SUNROOF	DOOR	Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);Benzo(a)pyrene(50-32-8);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Imidazolidine-2-thione(96-45-7)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)

ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Ethylenediamine(107-15-3);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	TBBA(79-94-7);Boric acid(10043-35-3);Lead(7439-92-1);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-

		6);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED CUV (CD CUV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Melamine(108-78-1)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylacetamide(127-19-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Dodecamethylcyclohexasiloxane(540-97-6);C,C'-azodi(formamide)(123-77-3);4,4'-Isopropylidenediphenol(80-05-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Tris(2-chloroethyl) phosphate(115-96-8)
DOOR SUNROOF	DOOR	Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);Benzo(a)pyrene(50-32-8);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Imidazolidine-2-thione(96-45-7)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)

ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Ethylenediamine(107-15-3);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	TBBA(79-94-7);Boric acid(10043-35-3);Lead(7439-92-1);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-



		6);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED CUV Plug-in Hybrid (CD CUV PHEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead-monoxide(1317-36-8);Dicyclohexyl-phthalate(84-61-7);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	BUMPER	C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OURSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Chromium-trioxide(1333-82-0);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Dicyclohexyl-phthalate(84-61-7)
	WHEEL TIRE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);1,2-Dimethoxyethane(110-71-4)
	THE OTHERS	Lead(7439-92-1);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Bis(4-chlorophenyl) sulfon(80-07-9)
	DOOR SUNROOF	DOOR
HOOD		Imidazolidine-2-thione(96-45-7)
SUNROOF		Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3)
TRUNK TAIL GATE		Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7)
THE OTHERS		Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2)
ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-

		titanium-trioxide(12060-00-3);Dicyclohexyl-phthalate(84-61-7);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
ENGINE ROOM	ENGINE TRANSMISSION	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Imidazolidine-2-thione(96-45-7);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);C,C'-azodi(formamide)(123-77-3);Bis(4-chlorophenyl) sulfon(80-07-9)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Hexahydromethylphthalic-anhydride(25550-51-0);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6)
INTERIOR	AIR BAG	
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Boric acid(10043-35-3);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	HEADLINING	Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);TBBA(79-94-7)
	SEAT ARM REST	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Dicyclohexyl-phthalate(84-61-7)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3)
STEERING SUSPENSION	SUSPENSION	
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	Cobalt chloride(7791-13-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);1-Propanol, 2,3-dibromo-

		(96-13-9);1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene(13560-89-9)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED Plug-in Hybrid (CD PHEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead-monoxide(1317-36-8);Dicyclohexyl-phthalate(84-61-7);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	BUMPER	C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OURSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Chromium-trioxide(1333-82-0);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Dicyclohexyl-phthalate(84-61-7)
	WHEEL TIRE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);1,2-Dimethoxyethane(110-71-4)
	THE OTHERS	Lead(7439-92-1);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1)
	DOOR SUNROOF	DOOR
HOOD		Imidazolidine-2-thione(96-45-7)
SUNROOF		Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3)
TRUNK TAIL GATE		Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7)
THE OTHERS		Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2)
ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Dicyclohexyl-phthalate(84-61-7)

	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
ENGINE ROOM	ENGINE TRANSMISSION	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Imidazolidine-2-thione(96-45-7);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);C,C'-azodi(formamide)(123-77-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Hexahydromethylphthalic-anhydride(25550-51-0);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6)
INTERIOR	AIR BAG	
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Boric acid(10043-35-3);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);C,C'-azodi(formamide)(123-77-3)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	HEADLINING	Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);TBBA(79-94-7)
	SEAT ARM REST	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Dicyclohexyl-phthalate(84-61-7)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3)
	STEERING SUSPENSION	SUSPENSION
STEERING		
BATTERY	BATTERY & MANAGEMENT SYSTEM	Cobalt chloride(7791-13-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);1-Propanol, 2,3-dibromo-(96-13-9);1,6,7,8,9,14,15,16,17,17,18,18-

		Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene(13560-89-9)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED SHOOTING BRAKE (CD SB)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Melamine(108-78-1)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylacetamide(127-19-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Dodecamethylcyclohexasiloxane(540-97-6);C,C'-azodi(formamide)(123-77-3);4,4'-Isopropylidenediphenol(80-05-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Tris(2-chloroethyl) phosphate(115-96-8)
DOOR SUNROOF	DOOR	Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);Benzo(a)pyrene(50-32-8);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Imidazolidine-2-thione(96-45-7)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)



ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Ethylenediamine(107-15-3);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	TBBA(79-94-7);Boric acid(10043-35-3);Lead(7439-92-1);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-

		6);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED WAGON (CD WGN)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Melamine(108-78-1)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclotetrasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylacetamide(127-19-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclotetrasiloxane(541-02-6);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Dodecamethylcyclotetrasiloxane(540-97-6);C,C'-azodi(formamide)(123-77-3);4,4'-Isopropylidenediphenol(80-05-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Tris(2-chloroethyl) phosphate(115-96-8)
DOOR SUNROOF	DOOR	Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);Benzo(a)pyrene(50-32-8);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Imidazolidine-2-thione(96-45-7)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclotetrasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)

ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Ethylenediamine(107-15-3);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	TBBA(79-94-7);Boric acid(10043-35-3);Lead(7439-92-1);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Octamethylcyclotetrasiloxane(556-67-2)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-

		6);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] CEED WAGON Plug-in Hybrid (CD WGN PHEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead-monoxide(1317-36-8);Dicyclohexyl-phthalate(84-61-7);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	BUMPER	C,C'-azodi(formamide)(123-77-3)
	GLASS GLASS MOULDING	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OUTSIDE MIRROR	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Chromium-trioxide(1333-82-0);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Dicyclohexyl-phthalate(84-61-7)
	WHEEL TIRE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);1,2-Dimethoxyethane(110-71-4)
	THE OTHERS	Lead(7439-92-1);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Bis(4-chlorophenyl) sulfon(80-07-9)
DOOR SUNROOF	DOOR	Lead(7439-92-1);Boric acid(10043-35-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Benzo(a)pyrene(50-32-8);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3)
	TRUNK TAIL GATE	Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2)

ELECTRIC CONTROL	ELECTRIC CONTROL	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Dicyclohexyl-phthalate(84-61-7);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
ENGINE ROOM	ENGINE TRANSMISSION	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Imidazolidine-2-thione(96-45-7);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);C,C'-azodi(formamide)(123-77-3);Bis(4-chlorophenyl) sulfon(80-07-9)
	HEATER & COOLING UNIT	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Hexahydromethylphthalic-anhydride(25550-51-0);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6)
INTERIOR	AIR BAG	
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Boric acid(10043-35-3);Diboron-trioxide(1303-86-2);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	CRASH PAD	TBBA(79-94-7);Lead-monoxide(1317-36-8);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead-titanium-trioxide(12060-00-3);Alkanes, C16-35, chloro(85049-26-9);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	HEADLINING	Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);TBBA(79-94-7)
	SEAT ARM REST	Lead(7439-92-1);TBBA(79-94-7);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dinitrate(10141-05-6);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING WHEEL GEAR SHIFT LEVER	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Dicyclohexyl-phthalate(84-61-7)
	SWITCHES CONTROLLER	Lead(7439-92-1);Lead-monoxide(1317-36-8);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7)
	THE OTHERS	Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3)
	STEERING SUSPENSION	SUSPENSION
STEERING		

BATTERY	BATTERY & MANAGEMENT SYSTEM	Cobalt chloride(7791-13-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);1-Propanol, 2,3-dibromo-(96-13-9);1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene(13560-89-9)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.