



Movement that inspires

SVHC List

[KIA MOTORS EUROPE SOUL EV (SK3 EV)]

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Tris(nonylphenyl)phosphite(26523-78-4);Nonylphenol(25154-52-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8)
	BUMPER	Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Lead titanium zirconium oxide(12626-81-2);Di-(2-ethylhexyl)phthalat(117-81-7);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2)
	GLASS GLASS MOULDING	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OURSIDE MIRROR	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6);Lead(7439-92-1);4,4'-Isopropylidenediphenol(80-05-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Boric acid(10043-35-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	WHEEL TIRE	Lead(7439-92-1);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4)
	THE OTHERS	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);Di-(2-ethylhexyl)phthalat(117-81-7);Melamine(108-78-1);Imidazolidine-2-thione(96-45-7);Lead(7439-92-1)
	DOOR SUNROOF	DOOR
HOOD		
SUNROOF		2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate(15571-58-1);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);TBBA(79-94-7)
TRUNK TAIL GATE		Imidazolidine-2-thione(96-45-7);Lead(7439-92-1)
THE OTHERS		Lead titanium zirconium oxide(12626-81-2);Lead(7439-92-1);Lead-monoxide(1317-36-8)
ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);Lead(7439-92-1);1,2-Dimethoxyethane(110-71-4);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Tris(2-chloroethyl) phosphate(115-96-8)

	WIRING HARNESS	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Di-(2-ethylhexyl)phthalat(117-81-7);C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Boric acid(10043-35-3)
ENGINE ROOM	ENGINE TRANSMISSION	Di-(2-ethylhexyl)phthalat(117-81-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Nonylphenol(25154-52-3);Decabromodiphenylether(1163-19-5);Boric acid(10043-35-3);TBBA(79-94-7)
	HEATER & COOLING UNIT	C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Bis(4-chlorophenyl) sulfon(80-07-9)
	THE OTHERS	Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Ethoxyethyl acetate(111-15-9);TBBA(79-94-7);Boric acid(10043-35-3);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);N,N-Dimethylacetamide(127-19-5);2-Ethoxyethanol(110-80-5)
INTERIOR	AIR BAG	
	CONSOLE	Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Lead(7439-92-1);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Nonoxinol(9016-45-9);Boric acid(10043-35-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	CRASH PAD	Lead-monoxide(1317-36-8);TBBA(79-94-7);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8)
	HEADLINING	Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Melamine(108-78-1)
	SEAT ARM REST	Lead(7439-92-1);4,4'-Isopropylidenediphenol(80-05-7);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Imidazolidine-2-thione(96-45-7);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	SEAT BELT PRETENTIONER	Lead(7439-92-1);TBBA(79-94-7)
	STEERING WHEEL GEAR SHIFT LEVER	N,N,N',N'-Tetramethyl-4,4'-methylenedianiline(101-61-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Diboron-

		trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);1-Methyl-2-pyrrolidone(872-50-4)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1)
	THE OTHERS	C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);TBBA(79-94-7);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene(13560-89-9);Lead-titanium-trioxide(12060-00-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);Lead(7439-92-1);Imidazolidine-2-thione(96-45-7)
	STEERING	Melamine(108-78-1)
BATTERY	BATTERY & MANAGEMENT SYSTEM	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Cobalt-dinitrate(10141-05-6);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Boric acid(10043-35-3)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.