



Movement that inspires

## SVHC List

### [KIA MOTORS EUROPE] STONIC (YB CUV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Cobalt-dinitrate(10141-05-6);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Dicyclohexyl-phthalate(84-61-7);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);Boric acid(10043-35-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Tris(nonylphenyl)phosphite(26523-78-4);Nonoxinol(9016-45-9);Diboron-trioxide(1303-86-2)
	BUMPER	Melamine(108-78-1);2-Ethoxyethyl acetate(111-15-9);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Dodecamethylcyclotetrasiloxane(540-97-6);Octamethylcyclotetrasiloxane(556-67-2);Lead(7439-92-1);2-Ethoxyethyl acetate(111-15-9);C,C'-azodi(formamide)(123-77-3);Lead titanium zirconium oxide(12626-81-2);
	GLASS GLASS MOULDING	Lead(7439-92-1);Melamine(108-78-1);Diboron-trioxide(1303-86-2)
	OUTSIDE LAMP OUTSIDE MIRROR	1-Propanol, 2,3-dibromo-(96-13-9);TBBA(79-94-7);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-8)
	WHEEL TIRE	Lead(7439-92-1)
	THE OTHERS	Melamine(108-78-1);Di-(2-ethylhexyl)phthalat(117-81-7);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead(7439-92-1);Bis(4-chlorophenyl) sulfon(80-07-9)
	DOOR SUNROOF	DOOR
HOOD		Lead(7439-92-1)
SUNROOF		Cobalt(II) nitrate hexahydrate(10026-22-9);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Octamethylcyclotetrasiloxane(556-67-2);Lead(7439-92-1)
TRUNK TAIL GATE		Cobalt-dinitrate(10141-05-6);Di-(2-ethylhexyl)phthalat(117-81-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);TBBA(79-94-7)
THE OTHERS		Lead titanium zirconium oxide(12626-81-2);Lead-monoxide(1317-36-8);Lead(7439-92-1)

ELECTRIC CONTROL	ELECTRIC CONTROL	Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);TBBA(79-94-7);Lead(7439-92-1);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);1,2-Dimethoxyethane(110-71-4);Melamine(108-78-1)
	WIRING HARNESS	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);Decamethylcyclopentasiloxane(541-02-6);Octamethylcyclotetrasiloxane(556-67-2)
ENGINE ROOM	ENGINE TRANSMISSION	Imidazolidine-2-thione(96-45-7);1-Methyl-2-pyrrolidone(872-50-4);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);N,N-Dimethylformamide(68-12-2);Benzene-1,2,4-tricarboxylic acid 1,2-anhydride(552-30-7);2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol(3864-99-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);N,N-Dimethylacetamide(127-19-5);Ethylenediamine(107-15-3);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Cobalt-dinitrate(10141-05-6)
	HEATER & COOLING UNIT	Tris(2-chloroethyl) phosphate(115-96-8);Lead-titanium-trioxide(12060-00-3);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Lead(7439-92-1);TBBA(79-94-7)
	THE OTHERS	Boric acid(10043-35-3);Melamine(108-78-1);2-Ethoxyethanol(110-80-5);2-Ethoxyethyl acetate(111-15-9);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Octamethylcyclotetrasiloxane(556-67-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);1-Methyl-2-pyrrolidone(872-50-4);Imidazolidine-2-thione(96-45-7)
INTERIOR	AIR BAG	
	CONSOLE	Nonoxinol(9016-45-9);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	CRASH PAD	Boric acid(10043-35-3);C,C'-azodi(formamide)(123-77-3);Nonoxinol(9016-45-9);Tris(2-chloroethyl) phosphate(115-96-8)
	DISPLAY	Cobalt(II) nitrate hexahydrate(10026-22-9);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);Melamine(108-78-1);Bis(2-methoxyethyl) ether(111-96-6);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Hexahydromethylphthalic-anhydride(25550-51-0);2-Methylimidazole(693-98-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);TBBA(79-94-7)
	HEADLINING	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);TBBA(79-94-7)
	SEAT ARM REST	TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8);Cobalt(II) nitrate hexahydrate(10026-22-9)
	SEAT BELT PRETENTIONER	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);Cobalt-dichloride(7646-79-9)

	STEERING WHEEL GEAR SHIFT LEVER	TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	SWITCHES CONTROLLER	Di-(2-ethylhexyl)phthalat(117-81-7);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead(7439-92-1)
	THE OTHERS	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Imidazolidine-2-thione(96-45-7)
STEERING SUSPENSION	SUSPENSION	Lead(7439-92-1);4,4'-Isopropylidenediphenol(80-05-7);Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3)
BATTERY	BATTERY & MANAGEMENT SYSTEM	Melamine(108-78-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead(7439-92-1);TBBA(79-94-7)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.